



811 Main St.  
Suite 3400  
Houston, TX 77002

P: (832) 519.2200  
F: (832) 519.2250  
www.Crestwoodlp.com

RECEIVED

NOV 04 2019

Enforcement and Compliance  
Assurance Division

October 30, 2019

Air Compliance Manager  
Wyoming Department of Environmental Quality  
Air Quality Division  
200 W 17<sup>th</sup> St  
Cheyenne, WY 82001

Subject: NSPS Subpart OOOOa Annual Report  
Reporting Period: August 2, 2018 through August 1, 2019  
Converse County, Wyoming

Dear Sir or Madam:

Crestwood Midstream Partners LP (Crestwood), on behalf of Jackalope Gas Gathering Services, LLC, is submitting the attached New Source Performance Standards (NSPS) Subpart OOOOa Annual Report for the compliance period of August 2, 2018 through August 1, 2019 (determined in accordance with 40 CFR §60.5410a). This report includes information on affected facilities located at the following:

Facility	Affected Facility ID
Bucking Horse Gas Plant	BKE00807, C06, ENG013
Pale Horse Compressor Station	N6W0067, CE-11, ENG011
	Fugitive Emissions Components

Should you require any additional information, please contact Kaitlyn Carter at (713) 380-3249 or via e-mail at Kaitlyn.Carter@crestwoodlp.com.

Sincerely,

(b) (6)

Kaitlyn Carter  
Senior Air Quality Specialist

Attachments: Certification of Truth, Accuracy, and Completeness  
40 CFR 60 Subpart OOOOa Annual Report

cc: U.S. EPA Region 8 – Denver, CO

Connections  
for America's  
Energy

**Attachment 1 – Certification of Truth, Accuracy, and Completeness**

---



811 Main St.  
Suite 3400  
Houston, TX 77002

P: (832) 519-2200  
F: (832) 519-2250  
www.Crestwoodlp.com

## Certification of Truth, Accuracy, and Completeness

Responsible Official / Delegated Authority

Name: (Last) Hansen (First) Ben

Title Vice President, Operations

Street or P.O. Box 811 Main Street

City Houston State TX ZIP 77002

Telephone (832) 519-2200

I, Ben Hansen, certify that based on information and belief formed after reasonable inquiry, the statements and information in the document are true, accurate, and complete.

Signature (b) (6) Date Oct 30 2019

Connections  
for America's  
Energy®

**Attachment 2 – 40 CFR 60 Subpart OOOOa Annual Report**

---

**40 CFR 60 Subpart OOOOa Annual Report - Site Information**  
**Jackalope Gas Gathering Services, LLC - Converse County, Wyoming**  
**Reporting Period - August 2, 2018 through August 1, 2019**

Facility Site Name	Description of Site Location	Latitude	Longitude	Responsible Agency Facility ID
Bucking Horse Plant	From Riverbend Dr/WY-59, Douglas, WY 1) Head West onto Monroe St (Pass under I-25) ~0.2 mi; 2) Turn Right onto Cold Springs Rd/WY-91 ~3.0 mi; 2) Turn Left to stay on Cold Springs Rd/ WY-91 ~1.6 mi; 3) Destination is on the Right.	(b) (9)		F025806
Pale Horse Compressor Station	From Center St, Douglas, WY 1) Head North on 4th St/WY-59 ~8.7 mi; 2) Turn Right onto Flat Top Rd ~7.7 mi; 3) Turn Left at fork onto unnamed road ~0.9 mi; 4) Destination is on the Left.			F025814

**40 CFR 60 Subpart OOOOa Annual Report - Fugitive Emissions Components**  
**Jackalope Gas Gathering Services, LLC - Converse County, Wyoming**

Reporting Period - August 2, 2018 through August 1, 2019

Survey Summary Report	
Company	Trihydro Corporation
Facility	Pale Horse
Facility Type	Compressor Station

Survey Information			
Date	6/27/2019	OGI Operator	Kurt Benson
Start Time	12:50:00	Training Completed	Infrared Training Center - Americas
End Time	14:09:00	Years of Experience	4 years 3 months
Sky Conditions	Mostly Clear	Max Wind Speed	7
Instrument Used	FLIR GFX320	Ambient Temperature	84

Deviations from Monitoring Plan	
Yes/No	Reason for Deviation if "Yes"
No	--

Leaks				
Component Tag	Component Type	Repaired per 60.5397a(h)	Date of Repair	Resurvey Method
1564	Connector	Yes	6/28/2019	Method 21- Soap Bubbles
1563	Connector	Yes	7/19/2019	Method 21- Soap Bubbles
--	Thief Hatch	Yes	7/12/2019	Removed from Service
1565	Connector	Yes	7/1/2019	Method 21- Soap Bubbles

Total Leaks Detected	
Component Type	Count
Thief Hatch	1
Connector	3

Delay of Repair		
Component Tag	Component Type	Reason for Delay
--	--	--

Difficult/Unsafe to Monitor (DTM or UTM) Components		
DTM or UTM	Component Type	Count
--	--	--



40 CFR 60 Subpart OOOOa Annual Report - Reciprocating Compressor Affected Facility  
Jackalope Gas Gathering Services, LLC - Converse County, Wyoming  
Reporting Period - August 2, 2018 through August 1, 2019

Facility	Compressor ID	Initial Start Date	Most Recent Rod Packing Replacement Date	Are emissions from the rod packing controlled through a closed vent system?	Hours of Operation
Bucking Horse Gas Plant	BKE00807, CD6, ENG013	12/17/2018	—	No	5,690
Pale Horse Compressor Station	N6W0067, CE-11, ENG011	5/10/2019	—	No	1,811